

IEQ SCHOOL DATA BASE									
School Name: Marriotts Ridge			Principal: Tammy Goldeisen			DATE: 1-9-17			
IEQ Team Leader: Cameron Rahnama			IEQ System Leader: Greg Maciulla						
LOOK-FORS	ROOM/LOCATION	COMMENTS	ADMIN	FACILITIES	WORK ORDER NUMBER of POTENTIAL IEQ	DATE ASSIGNED	COMPLETION DATE	30 DAY REVISIT	CLOSED
1. No unusual or offensive odors, or temperature discomfort	254,234	Bad smell, funky smell		x	17990	1/18/2017			
2. No Air Fresheners	Data Clerk Office, 216	Air Freshener, air freshener	x			1/10/2017	1/10/2017		
3. No food, dirty lunch boxes, etc. left in room	2nd floor planning, 250, Testing office, 354	unsealed food, unsealed candy, unsealed candy, unsealed food	x			1/10/2017	1/10/2017		
4. Vents are clean and unobstructed	Restroom by 200, 244, TC -4, 3rd floor staff restroom by stairwell 3, 338, outside of 342, stairwell 2, 3rd floor custodial closet	Dusty Vents, dusty vents, dusty vents, dusty vents, vent blocked, cob webs in vent, dusty vent, dusty exhaust fan	x			1/18/2017			
5. Temperature sensors are not blocked	320 closet	Thermo blocked	x			1/18/2017			
6. Area appears clean and dust free	Main Gym, Wrestling Room, Band Room, 117	Dust behind bleachers, dusty, dusty, trash on floor	x			1/10/2016			
7. No signs of animal infestation									
8. Ceiling tiles present; no broken, stained, or painted	117, Training room, weight room, 104, 102, practice room 3, 105, hvac room 17, 111, 124, 123(closet), custodial office, Media, 231, 228 room and Closet, 226, 236, 222, 208, 207, 250, 246, science prep 2nd floor, 312 hallway, 312 class, Stairwell 3 on 3rd floor by TV, Stairwell 3, 3rd floor staff restroom, Hallway by 330, 336, HVAC room 323(science prep), 342, 344, 346 (multiple), 348 by cutodial room, 349, 349/350 Hallway, Elec room #6, 300 (multiple), Hallway by 300, Hallway by 305	3 broken CT, 2 CT out, 2 CT stain, 1 CT broke, 1 CT Stain, 2 CT stain, 1 CT stain, 1 CT stain, 1 CT crack, 1 CT Stain, 1 CT stain, 1 CT crack, 1 CT crack, 1 CT crack, 1 CT, 1 CT stain stain, CT stain, 1 CT crack, 1 CT stain, 2 CT stain, 1 CT, 1 CT stain, 1 CT stain, 1 CT hole, 1 CT stain, 1 CT stain, 2 CT stain, CT stain, CT stain, CT stain, CT, CT stain and need to be cut better stain CT, CT stain, CT stain, CT stain, CT stain, CT crack, CT stain, CT stain, CT stain, CT stain, 2 CT stain, CT Stain, CT holes and Stains, CT stain, CT stain	x	x	17896, 17406	1/17/2017			
9. Walls show no signs of water damage/mildew/ paint irregularities	Server room off media, 222 boys room, 216, 212, stairwell 3, 344 CMU, 344, 349	Crack in wall, rust spotting, water stain on window, condensate on windows, CMU crack, CMU water damage, cracked tile by window, CMU crack		x	174992, 174994, 18253, 18002, 18038, 18001		11/18/17		





<b>IEQ SCHOOL DATA BASE</b>									
<b>School Name: Marriotts Ridge</b>			<b>Principal: Tammy Goldeisen</b>			<b>DATE: 1-9-17</b>			
<b>IEQ Team Leader: Cameron Rahnama</b>					<b>IEQ System Leader: Greg Maciulla</b>				
37. Exterior veneer intact									
38. Outside lights working and intact									
39. Gutters and downspouts clear/working									
40. No stains from roof on outside walls									
41. Bins from garbage and recycling clearly marked									
42. Hard surfaces (sidewalks, etc.) cleared of any turf application									
43. Proper maintenance of planted beds and other vegetation									
44. Landscaping and turf look healthy and disease free									
<b>COMMENTS:</b>									
Additional items include: Hallway by room 212 = Missing locker 17995. Storage room in room 200 n= Air flow installed incorrectly 18284. Room 234 =Escushion missing 18251. Server room in media = crack in wall 17992, Room 322 = sprinkler escushion missing. TC-5 = Leak. Room 342 = Leaky faucet.									